



Connection Diagram of Iotron™ Sensors with Signet 9030 Preamplifiers to Signet 9030 Transmitters

Cable Color Coding	Instrument Terminal Name	Signet Terminal Number
Red	+ V	10
Black	- V	11
Green	T +	12
Brown	A <sub>in</sub> (Signal)	13
White	ISO (Ref. + T-)	14

**Note: Set gain = +1 in the instrument.**