



INITIAL SETTINGS & CONFIGURATION:

- (1) SELECT SENSOR TYPE AS "OTHER"
- (2) SET CELL CONSTANT TO 4.8
- (3) ZERO SENSOR IN AIR
- (4) PERFORM WET CALIBRATION WITH STANDARD SOLUTION OR PROCESS MEDIA

Advanced Sensor Technologies, Inc.
 Orange, California 92868 -1011 USA
 Toll-Free: 888-969-2784
 Phone: 714-978-2837
 Fax: 714-978-6339
 Website: <http://www.astisensor.com>

NOTES UNLESS OTHERWISE SPECIFIED:



DRAWN 9/18/08		TITLE	
CHECKED		ASTX-37PP TORROIDAL SENSOR WIRING TO ROSEMOUNT 1056 / 1057 / 56	
APPROVED		SCALE NONE	DRAWING NO.
		SHEET 1 OF 1	REV.
		ASTX-37PP-1056	