



Connection Diagram of Iotrontm Sensors to All External Preamplifiers

Cable Color Coding	Signal Name	External Terminal Board Number
Green	TC	1
Yellow	TC	2
Black	Reference Electrode	3
Red	Liquid Earth (solution ground)	4
Clear	Measuring Electrode	5