



Connection Diagram of Iotron™ Sensors with 1050 Preamplifiers to Uniloc 1050 Transmitters

Cable Color Coding	Instrument Terminal Name	Uniloc Terminal Number
White	+ 5 VDC	1
Green	- 8 VDC	2
Black	pH Signal	3
Yellow	Reference	4